

tekmar [®] form	Service Bulletin	SB 028 11/12/2002	v0011
------------------------------------	-------------------------	-----------------------------	--------------

Programmable Thermostat 512

Dear Representative,

In certain situations, the second-stage may not turn on in the Programmable Thermostat 512. This only occurs when operating in the Two-Stage mode and the thermostat is operating with a cycle length that is longer than 20 minutes.

This can be corrected in the field by selecting a fixed cycles per hour of 3 or higher.

If you have any questions, please contact your local tekmar representative.

Sincerely yours,

Clifford McNeill
tekmar Control Systems Ltd.